

# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 2

Sewershed : Gwynn Falls

Company : URS

Date : 09/25/2008

Test to be Performed :  
Smoke : X Dyed Water :   

Ground Condition :  
Dry : X Damp :    Wet :   


Supervisor : Ryan Lamont

Manhole ID : S05SS\_007MH




Test ID : S1032-022048

Notifications (Residents, Fire, 311) :  
Yes

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



LEGEND		Defect Code	Defect Description	Defect Code	Defect Description
		SL	Service Lateral	CB	Catch Basin
		TJ	Transition Joint	SD	Storm Ditch
		DD	Driveway Drain	SWMH	Storm Manhole
		WWD	Window Well Drain	MAIN	Main Sewer
		STRD	Stairwell Drain	SANMH	Sewer Manhole
		AD	Area Drain	CO	Cleanout
		DS	Downspout	OTHER	Other
		DSC	Downspout Connection	IOB	Inside of Building
		FD	Foundation Drain		

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 2 of 2
Sewershed : <u>Gwynn Falls</u>	Company : <u>URS</u>	Date : <u>09/25/2008</u>
Test to be Performed : Smoke : <u>X</u> Dyed Water : <u>  </u>	Ground Condition : Dry : <u>X</u> Damp : <u>  </u> Wet : <u>  </u>	Supervisor : <u>Ryan Lamont</u>
Manhole ID : <u>S05SS_007MH</u>	Test ID : S1032-022048	Notifications (Residents, Fire, 311) : <u>Yes</u>
Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)		
<div> <div> ID <div>  <p>Location: N/A; Type: Cleanout; Smoke: Medium; Status: Private Property</p> </div> <div> Landscape <div>  </div> </div> <div> Defect <div>  </div> </div> </div> </div>		